Brady Printer Driver v3.x Release Notes

August, 2012

New Features

- Added **BBP®33** *Label Printer* Driver
- **BBP®11** *Label Printer* New updates to support **MARKWARE™** GHS (Globally Harmonized System) templates.

May, 2012

NEW Features

- Added **BMP®51** *Label Printer* Driver
- Added **BMP®53** *Label Printer* Driver
- Added **BSP®61** *Label Printer* Driver

Defect Fixes

- Added support for **WRAPTOR™** *Wire Marker System* printer on Windows 7, 64bit OS.
- Corrected port monitors for **GLOBALMARK®** *Industrial Label Maker* and **POWERMARK®** *Sign and Label Maker* printers:
  - GLOBALMARK printer port name in POWERMARK USB description.
  - POWERMARK: Scrambled graphic when using 15 inch panel ribbon.
  - GLOBALMARK/POWERMARK connected on the same PC.

Service Notification Fixes

Product	Notification #	Resolution
BBP11	300352014	New driver on CD
BBP72	300371435	Windows 7 support
PowerMark	300388871	Install
PowerMark	300373489	Panel ribbon issue
PR+	300346886	New driver on CD
BBP71	300384682 300371174 300386812 300385285	Installation issues resolved by firmware change

June 2011

New Features

Versions 3.01 and 3.02

- Added full support for Windows 7, 32 and 64bit systems.
- Added Authenticode signature for Windows Authentication for each device.
- Added **BMP®71** *Label Printer* Driver.
- Added **BBP®31** *Label Printer* Driver.

Version 3.1

- Added a new printer driver installation application which combines all internal and external Brady drivers on the same CD.
- Added Printer Driver detection. The installation application will not install a new driver if a previous printer driver is detected.

Defect Fixes

- Version 3.10: Corrected port monitors for GLOBALMARK and POWERMARK printers.

Helpful Notes

- The only difference between Printer Driver version 3.01/3.02 and 3.10 is the port monitor correction for GLOBALMARK and POWERMARK, which was changed to match all internal Brady printers. **Note**: Although version numbers changed, the base driver code did not change.
- The Brady MRO printer drivers version 2.x (GLOBALMARK, POWERMARK, HANDYMARK and MINIMARK) are the same as version 3.x. The only difference is the USB driver name for GLOBALMARK and POWERMARK.

  Version 2.x works on Windows 7 32 bit, however, you must map the unknown device to the correct USB device for GLOBALMARK and POWERMARK printers. Version 2 drivers do not support Windows 7, 64-bit.
- The 3.x drivers are signed for Windows Authentication.
- Added a user-friendly install application for version 3.x. The installation documentation is located on the printer driver CD.
- Added previously released version 3.01 printer drivers for Brady Internal OEM to the Installation CD and changed the version to 3.10. No code changes were made to the printer drivers.
- Currently do not have a Windows 7, 64- bit driver for the WRAPTOR printer. WRAPTOR firmware needs to be changed to support 64 bit.
- The following is a compatibility matrix for the driver version and operating system:

Brady Printer Driver Version	Version 2.x	Version 3.x
OS Version	Windows XP Windows Vista	Windows XP Windows Vista Windows 7 32- & 64-bit