



CortexJPOS™ Device Manager for Windows ReadMe Version 6.1.1

May 2021

This JPOS package contains the following files	
CortexJPOS_6.1.1_Windows ReadMe.pdf	This document
CortexJPOS User Manual.pdf	JPOS User Manual
32-bit Architecture CortexJPOSSetup-6.1.1-Windows_x86.exe	Installation executable for 32-bit x86-64 Intel / AMD processor architectures
64-bit Architecture CortexJPOSSetup-6.1.1-Windows_x86-64.exe	Installation executable for 64-bit x86 Intel / AMD processor architectures

PLEASE NOTE!

- This readme file contains information about the latest version of Code Corporation's CortexJPOS™ for Windows package.
- Download the CortexJPOS package from the appropriate product page on the Code website or by contacting Code Technical Support at support@codecorp.com.
- Support for all Code products is available from the Code website at www.codecorp.com or by contacting Code Technical Support at support@codecorp.com.

Table of Contents

1. NEW FEATURES IN THIS RELEASE	4
2. ENHANCEMENTS/IMPROVEMENTS/FIXES	4
3. CHANGES TO DEFAULT SETTINGS	5
4. OUTSTANDING ISSUES	5
5. SOFTWARE/READER TOOL COMPATIBILITY	6
6. TECHNICAL SUPPORT INFORMATION	7

1. NEW FEATURES IN THIS RELEASE

The following are notable new features in this release.

- None

2. ENHANCEMENTS/IMPROVEMENTS/FIXES

CortexJPOS 6.1.1 (2021-05)

- Added support for CR2700 paired with A271.
- Added support for CR1100
- Added support for CR5200
- Updated JPOS installer

CortexJPOS 6.0 (2018-02)

The following are JIRA issues resolved by this release. Note feature requests are in **bold** while bugs are in normal text. Note the italicized JIRA issues are issues found during Code's internal testing.

- JPOSPSW-1 (Bugzilla 1217) – An error message should come up letting the user know that JPOS can't run if CortexTools/CortexWedge is running
- JPOSPSW-2 (Bugzilla 1216) – JPOS will not ignore modems that are connected to the computer
- JPOSPSW-3 (Bugzilla 1098) – Script error on application load
- JPOSPSW-4 (Bugzilla 1083) – CortexJPOS driver crashes on second attempt to claim a device when none present
- JPOSPSW-6 (Bugzilla 288) – After adding a device in the OPOS/JPOS device manger screen, the image displayed next to the device is the same (CR1000) for all readers
- JPOSPSW-7 (Bugzilla 583) – Reader de-enumerates / re-enumerates continuously if it decodes something during POSTest "claim"
- **JPOSPSW-8 – Add software support for 8200-family readers using CodeUtil2 SDK (CodeUtil2.dll)**
- JPOSPSW-10 – Device manager's "Cancel" button label shows "Can..."
- JPOSPSW-11 – The device name field is grayed out when adding a serial device
- *JPOSPSW-14 – Message comes up to configure 950 and 8200 readers that have already been added to the device manager*
- JPOSPSW-15 – InstallShield incorrectly gives an error on Java version
- JPOSPSW-16 – If CortexJPOS works with JRE 9, installation should state "JRE 8 or later"
- JPOSPSW-17 – Message saying you have to uninstall the old version of JPOS should come up
- *JPOSPSW-18 – A serial device is not detected when it is connected and requires the appropriate platform selection (CT8000- versus CT8200-technology)*
- JPOSPSW-19 – Connected serial reader shows it is not present on re-opening Device manager
- JPOSPSW-20 – JPOS won't install on a computer with Java version 8 update 111
- *JPOSPSW-21 – JPOS doesn't list the CR5000 when it detects it*
- *JPOSPSW-23 – Message about "device claim failed" comes up when both the sample application and device manager are open*
- *JPOSPSW-24 – No matter what barcode is scanned the only output is the same*

- JPOSPSW-27 – Change JPOS zip file name
- JPOSPSW-30 – When clicking on the disconnect button when a 950 and 8200 reader is disconnected, the sample app crashes
- JPOSPSW-35 – CR1400 was disconnected but no message came up indicating it was not present
- JPOSPSW-36 – Only 8200 readers can be configured as a serial device
- JPOSPSW-37 – JPOS occasionally crashes when first launched
- JPOSPSW-38 – JPOS sample app crashes when attempting to connect to 8200-family serial reader

CortexJPOS 4.0.5 (2013-10-23)

- Connected devices not listed in device manager after deleting the connected device profile name and clicking the "Add device" button without restarting the application
- CR900 Device not detected in JPOS device Manager
- Devices that are added already in the device manager with the option "Lock the hardware" still listed in the "Available new device" options after restarting the JPOS device manager
- Device name for the connected devices not added when we rename the default logical device name in JPOS Device manager
- Serial port device not detected in JPOS device manager
- Configuration for single reader of the particular type is not working for multiple devices
- Sample application crashed when unplugging connected devices

CortexJPOS 3.0 (2012-02-27)

- Device manager not detecting the device connected in the sample application and asks to remove the device name while opening the device manager after opening the sample application
- Option for removing individual device from missing devices in the device manager is not available

CortexJPOS 2.0 (2012-02-06)

- Initial Release

3. CHANGES TO DEFAULT SETTINGS

CortexJPOS 6.1.1

- None

CortexJPOS 6.0

- None

4. OUTSTANDING ISSUES

- A serial-based, 8000-family reader requires the user to select a COM port with the normal COMx port name, while a serial-based, 8200-family reader (CR950, CR8200) requires the user to select a COM port with the "8200" COMx(8200) port name. This situation arises because CortexJPOS must use an 8000-family SDK to communicate with 8000-family readers and an 8200-family SDK to

communicate with 8200-family readers, and their communication protocols are incompatible. Until the CortexJPOS application has a solution provided by the coming enhancement of the SDKs to permit automatic detection and reader differentiation before the application must use an SDK, the user will need to select the reader using a differentiated COM port name so CortexJPOS "knows" which SDK to use.

5. SOFTWARE/READER TOOL COMPATIBILITY

Recently upgraded CortexJPOS™ for Windows software is available for download from the Code Corporation website at codecorp.com/downloads.php or by contacting Code Technical Support via email at support@codecorp.com.

6. TECHNICAL SUPPORT INFORMATION

You may contact Code at:

Code Corporation
434 Ascension Way, Suite 300
Murray, UT 84123
USA

Voice: +1 801-495-2200

Fax: +1 801-495-0280

Email: support@codecorp.com

You can track new product releases, software updates and technical bulletins by visiting the Code web page at www.codecorp.com.

If you have technical questions, visit our website at www.codecorp.com for phone numbers and email addresses.

Disclaimer:

Copyright© 2012-2021 Code Corporation
All Rights Reserved

The software described in this ReadMe file may only be used in accordance with the terms of its License Agreement. No part of this publication may be reproduced in any form or by any means without written permission from Code Corporation. This includes electronic or mechanical means such as photocopying or recording in information storage and retrieval systems.

NO WARRANTY. Code Corporation provides this technical documentation AS-IS. Further, the documentation does not represent a commitment on the part of Code Corporation. Code Corporation does not warrant it is accurate, complete or error free. Any use of the technical documentation is at the risk of the user. Code Corporation reserves the right to make changes in specifications and other information contained in this document without prior notice, and in all cases, the reader should consult Code Corporation to determine whether Code Corporation has made any such changes. Code Corporation shall not be liable for technical or editorial errors or omissions contained herein; nor for incidental or consequential damages resulting from the furnishing, performance, or use of this material. Code Corporation does not assume any product liability arising out of or in connection with the application or use of any product or application described herein.

NO LICENSE. No license is granted, either by implication, estoppels, or otherwise, under any intellectual property rights of Code Corporation. Any use of hardware, software and/or technology of Code Corporation is governed by its own agreement.

The following are trademarks or registered trademarks of Code Corporation:

CodeXML®, Maker, QuickMaker, CodeXML® Maker, CodeXML® MakerPro, CodeXML® Router, CodeXML® Client SDK, CodeXML® Filter, HyperPage, CodeTrack, GoCard, GoWeb, ShortCode, GoCode®, Code Router, QuickConnect Codes, Rule Runner®, Cortex®, CortexRM, CortexMobile, Code, Code Reader, CortexAG, CortexStudio, CortexTools, Affinity®, CortexDecoder, CortexJPOS, CortexOPOS.

All other product names mentioned in this ReadMe file may be trademarks of their respective companies and are hereby acknowledged. The software and/or products of Code Corporation include inventions that are patented or that are the subject of patents pending.