A CAUTION ROTATE GUARD COLLAR DOWN

BEFORE THREADING
NEW JOB









Lockout Procedure

Air Compressor 1

Area 3

■ BR∆DY_®



REFLECTIVE



DANGER



Multicolor tags for Safety, Maintenance, Lean 5S


Printed on B30-255-851-WT-B using B30-R10000-KRYG-8 print ribbon





NORMAL SET POINT

185°F 200psi





We make products that make the world a safer and smarter place. From the depths of the ocean to outer space, from the factory floor to the delivery room —

we're just about everywhere you look.

For more information or to learn more about our innovative products, visit BradyID.com or call 1-888-272-3946.

USA Customer Service: 1-888-272-3946 Canada
Customer Service: 1-800-263-6179
BradyCanada.ca


Mexico Customer Service: 1-800-262-7777 Inside Sales: 1-800-262-7777 ext 177 BradyID.com.mx



S3700 Label Demo Board
MULTICOLOR + CUT SIGN AND LABEL PRINTER

Spark your creativity with this handy guide showcasing labels and signs produced by the versatile S3700 Multicolor & Cut Sign and Label Printer. Each example is displayed in actual size.









MULTI-SIGNS!

CUTOUT

ENCLOSURE-20

UPS SUBPANEL 6 ON BREAKER 41



MAKE-UP PUMP 106A

Disconnect Location: Panel 4501 on Level 2 Mezzanine

Lockout Procedure: LOP-P106A

AWARNING

ARC FLASH AND SHOCK HAZARD APPROPRIATE PPE REQUIRED

- Flash Hazard Boundry

FCV-18

8A-118 PA

DILUTION ST

- cal/cm2 Flash Hazard at 18 inches
- PPE Level (FR shirt & FR pants, or FR coverall, eye protection, hard ht, VR rubber or leather gloves
- Shock hazard when cover is open/removed
 - Limited Approach

LUBE POINT NO. 8 **Property of Jamer Co** Do Not Remove

Do Not Remove

Property of Jamer Corp. Do Not Remove

*

250 ml

1 PUMP **WEEKLY**

attention. Leaking gas fire: Do not extinguish, unless leak can be stoppe afetly. Eliminate all ignition sources i safe to do so. Store in a well-ve place. Store locked up.

See safety data sheet for

